

CERTIFICATION Notice

An Urgent Bulletin from CSA Group

Household Cooking Ranges No. 10A

(Supersedes Notice, Household Cooking Ranges No. 10, Ref. No: N15-160)

See Attachment 1 for Effective Dates.

Date: February 27, 2018

See Attachment 1 for Application Due Dates

Announcing: Publication of Revisions to Standard UL 858 (16th Edition), Household Electric Ranges

Class No: 2831 81, HEATERS - Household Cooking Ranges and Units Certified to US Standards

Who is affected?

Manufacturers of household electric cooking ranges, electric built-in ovens, and electric cooktops.

What do you do?

1. CSA Group Service Delivery staff will contact you to address compliance with each revision as applicable to the product designs covered in your affected Certification Reports. In addition to updates to your Certificate(s) of Compliance & Report(s), testing may be required to comply with these revisions.
2. Please respond within thirty (30) days of receiving CSA Group's "Application for CSA Certification Services" and "Quotation" communication. You must respond no later than the application dates listed in Attachment 1 in order to guarantee the update to your certification is completed by the corresponding effective dates shown in the same attachment. If testing is needed, we will inform you of the samples required.

Approvals:

The Notice - Household Cooking Ranges No. 10, issued on October 29, 2015, announced the publication of June 18, 2015 revisions to Standard UL 858 (16th Edition).

This Notice – Household Cooking Ranges No. 10A, announces the publication of August 30, 2017 revisions to Standard UL 858 (16th Edition) and will supersede the Notice - Household Cooking Ranges No. 10. The effective dates have not been affected.

New and currently certified household, electric cooking ranges, electric built-in ovens, and electric cooktops are required to comply with the applicable new and revised requirements detailed in the "Major Revisions" section below as of the specified effective dates.

Major Revisions:

See Attachment 2.

Background and Rationale:

The Abnormal Operation - Coil Surface Unit Cooking Oil Ignition Test procedure in Clause 60A, originally incorporated into the October 29, 2015 revisions to UL 858 (16th Edition), has been improved and published as August 30, 2017 revisions.

For questions specific to your file or products contact your CSA Group technical staff associate.

Go to <http://www.csagroup.org/services/testing-and-certification/product-listing/> and enter your Master Contract # and the class numbers associated with this Notice to determine which of your products are affected.

For technical questions on this Certification Notice

Contact Don Lee
by phone 416-747-4176, fax 416-747-4149
or e-mail don.lee@csagroup.org

The standard edition or amendments announced in this Notice may be used for certification as of the date of issue of this Notice. The "Effective date" in this Notice is the date on which the current requirements, applicable to Certified products listed in the affected class numbers, expire and the standard edition or amendments announced in this Notice become the only requirements that may be used for certification.

In the event that currently certified products do not comply with the latest requirements outlined in this Notice after the "effective date", the certification of such models may be discontinued.



Visit us at www.csagroup.org where you can click on "Contact Us" for the online phone listing of our Offices and Partners.

ATTACHMENT 1

Effective Dates

The effective date is June 18, 2017 for the following requirements:
revised stability test requirement in Clause 38.2.1; and
new sponge washing test in Clause 71.2.

Apply before March 18, 2017 to ensure your certification is completed by June 18, 2017.

The effective date is June 15, 2018 for the following requirements:
revised internal wiring VW1 flame rating requirement in Clause 10.8; and
new coil surface unit cooking oil ignition test in Clause 60A.

Apply before March 15, 2018 to ensure your certification is completed by June 15, 2018.

ATTACHMENT 2

Major Revisions

Clause(s)	Changes	File Review Required
2.1.1	Added definition of coil surface unit.	No
10.8	Revised requiring internal wiring to have a VW1 flame rating.	Yes
38.2.1	Revised the test load for the stability test from 75 lb. to 100 lb.	Yes
60A	Added a cooking oil ignition test to be conducted for appliances employing a coil surface unit. The test procedure was improved in the August 30, 2017 revisions to employ cast iron pans and provide an alternative test method.	Yes
71.2	Added a sponge washing test to be conducted on user accessible control areas.	Yes